

Windows 7 USB Port Installation Instructions

Plug the USB cable from the scanner into a USB port on the PC

New hardware found will be displayed, then after a minute, the PC will give up, briefly show a message that the device could not be installed.

Un zip the drivers that I emailed earlier and have available somewhere on your hard drive.

Click on the lower left corner Window Icon.

Click on Control Panel

Click on the Hardware and Sound choice.

Under "Devices and Printers" click on "Device Manager"

Double Click on the "USB Grader" device that is listed under "Other Devices"

Click the "Update Driver" button

Click the Browse my computer for driver software option

Navigate to the location on your hard drive where the Windows 7 USB Drivers are located and select.

Click Install. (Be patient.)

A warning screen will appear, Click the option: "Install this driver software anyway" selection.

You have now completed one half of the installation, the whole process will need to be repeated.

The selection in the listing has been changed from "USB Grader" to "USB Serial Port", double click on this listing.

Install again the same drivers and select again "Install this driver software anyway" option.

This time when it completes, the name in the listing will change back to "USB Grader" and it will show that it is properly installed.